

STRUCTURE LIST		
ITEM	QTY	STRUCTURE
1	3	BackWall-A
2	4	Corner Post
3	2	606 0992 2418 30




beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by: Steve Rendon		
Client: Image Options		
Project: Image_Options-Pop_Up-A		
Quotation/Order: 00000		
Description: Overview		1 / 4




beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by: Steve Rendon		
Client: Image Options		
Project: Image_Options-Pop_Up-A		
Quotation/Order: 00000		
Description: Dimensions		2 / 4



STRUCTURE LIST		
ITEM	QTY	STRUCTURE
1	22	306 0985 2411
3	3	BackWall-A_V2
6	4	Corner Post_V2
7	2	606 0992 2418 30





beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by:	Steve Rendon	
Client:	Image Options	
Project:	Image_Options-Pop_Up-A_V2	
Quotation/Order: 00000		
Description:	Overview	1 / 4




beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by:	Steve Rendon	
Client:	Image Options	
Project:	Image_Options-Pop_Up-A_V2	
Quotation/Order: 00000		
Description:	Dimensions	2 / 4



STRUCTURE LIST		
ITEM	QTY	STRUCTURE
1	4	Corner Post
2	2	606 0992 2418 30
3	1	BackWall-B
4	2	SideWall-B





beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by:	Steve Rendon	
Client:	Image Options	
Project:	Image_Options-Pop_Up-B	
Quotation/Order: 00000		
Description:	Overview	1 / 5




beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by: Steve Rendon		
Client: Image Options		
Project: Image_Options-Pop_Up-B		
Quotation/Order: 00000		
Description: Dimensions		2 / 5



STRUCTURE LIST		
ITEM	QTY	STRUCTURE
1	4	Corner Post
2	2	606 0992 2418 30
3	26	306 0985 2411
3	1	BackWall-B
4	2	SideWall-B





beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by:	Steve Rendon	
Client:	Image Options	
Project:	Image_Options-Pop_Up-B_V2	
Quotation/Order:	00000	
Description:	Overview	1 / 5




*beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.*



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by: Steve Rendon		
Client: Image Options		
Project: Image_Options-Pop_Up-B_V2		
Quotation/Order: 00000		
Description: Dimensions		2 / 5



STRUCTURE LIST		
ITEM	QTY	STRUCTURE
1	8	BackWall-A
2	8	606 0992 2418 30
3	1	CornerPost 4Sided
4	4	Corner Post 3 Sided
5	4	CornerPost 2 Way




beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by: Steve Rendon		
Client: Image Options		
Project: Image_Options-Pop_Up-C		
Quotation/Order: 00000		
Description: Overview		1 / 6




beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by:	Steve Rendon	
Client:	Image Options	
Project:	Image_Options-Pop_Up-C	
Quotation/Order: 00000		
Description:	Dimensions	2 / 6



STRUCTURE LIST		
ITEM	QTY	STRUCTURE
1	4	Corner Post 3 Sided
2	6	SideWall-B
3	2	BackWall-B
4	1	CornerPost 4Sided
5	4	CornerPost 2 Way
6	8	606 0992 2418 30





beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by:	Steve Rendon	
Client:	Image Options	
Project:	Image_Options-Pop_Up-D	
Quotation/Order: 00000		
Description:	Overview	1 / 7



beMatrix BVBA cannot be held responsible for the structural stability of the final implementation.
Possible extra charges for additional reinforcements or rigging are at client's expense.



80 Icon
Foothill Ranch, CA 92610
+1 (949) 586-7665
srendon@imageoptions.net

Copyright by
Image Options

Project Manager:		Date: 3/20/2020
Drawn by: Steve Rendon		
Client: Image Options		
Project: Image_Options-Pop_Up-D		
Quotation/Order: 00000		
Description: Dimensions		2 / 7